

№ 4019

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

11
20

DATE INSPECTED 12/14/38

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

5' 6"

HOUSE NO. 1037

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

5' 6" — 5' deep

WAS LATERAL AT CURB? Yes

NAME OF CONTRACTOR


Parley

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

10TH ST. N.E.

N



95'

M.H. 6-2-

SIGNED

John E. Humer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

11/14/39

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
N^o 4019
PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/14 19

RECEIVED OF

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.