

N^o. 4022FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED3
24DATE INSPECTED 12/24/38IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

69

HOUSE NO. WHITTIER SCHOOLDISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

69'

8" deep


WAS LATERAL AT CURB? Yes

NAME OF CONTRACTOR

Smart

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED:

Found lateral
Curb - went o
in street & lower
2 Pipe in streetOK
GC

SIGNED

John Thayer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

MAN, 2-1

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4022

PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/21 1930

RECEIVED OF Mr. James

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Board of Public Service

TO TAP Sanitary

SEWER, ON THE North

OF Art. D. Kane N.E.

AVE., TYPE OF STREET Driv.
ST.

THE PREMISES BEING LOT No. 7434

HOUSE No. Whitten D.L.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L.H. James

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.