## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 4027AND SIGNED WHEN RETURNED DATE INSPECTED 2/16/39 FIRST MANHOLE DOWN STREAM HOUSE NO. 4. BURTON AVE. M. SIZE OF PIPE USED \_\_\_\_\_\_ CURB LINE AND DEPTH WAS LATERAL AT CURB? NO NAME OF CONTRACTOR \_ WAS ATTACHED TO MAIN NO SHOW BY DIAGRAM RELATION OF CURB LINE FILED AT ENGINEER'S OFFICE REMARKS: MAIN 7'OFF CURB 9'DEEP

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE 1.0 4027PERMIT TO TAP SEWER MASSILLON, OHIO, THE PREMISES BEING LOT NO.  $\frac{\sqrt{2}}{\sqrt{2}}$ WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE. NAME OF CONTRACTOR \_\_\_\_ Note. This permit covers work outside of building only. Any work inside 1 of building is subject to Massillon Board of Health Regulations.