FOLLOWING DATA TO BE ANSWERED BY INSPECTOR N_{\odot}^{o} 4033 AND SIGNED WHEN RETURNED IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM House No. 322 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT ____ TO COVEDS! SIZE OF PIPE USED CURB LINE AND DEPTH WAS LATERAL AT CURB? GETHAND OF MOTOR MINES HOTH NAME OF CONTRACTOR WAS ATTACHED TO MAIN_ SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. 1 St St. S.W. FILED AT ENGINEER'S OFFICE

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE N_{\bullet}^{0} 4033 PERMIT TO TAP SEWER

	ri ka kwaraka ili umuli umuli muli makarawa na kata wa kata wa N	Woo shows tend Mass	ILLON, OHIO,	19
	RECEIVED OF	real proof History		FEE OF \$2
	A A A A	read one neighbor	J	Sick of Firs
FOR	WHICH PERMISSION IS GRA	NTED ASSESSED ASSESSED	Caroling to	a Aresa (A.) (4) de AA(A) A (4) (4) (4) (4) (4) (4) (4) (4)
TO TA	12 to		THE O	HOYTA DAW
OF	2 11	Ave	Type of Street	dit
		ST.,		
THE F	PREMISES BEING LOT No	<u> </u>	, House No	<u> </u>

NAME OF CONTRACTOR

RULES OF THE DEPARTMENT OF PUBLIC SERVICE

Note. This permit covers work outside of building only. Any work inside vof building is subject to Massillon Board of Health Regulations.