

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4038

DATE INSPECTED 5/18/39

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

174

HOUSE NO. WESLEY M. E. CHURCH.

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

174

9' d.

SIZE OF PIPE USED

4"

WAS LATERAL AT CURB?

Yes


WAS ATTACHED TO MAIN

Yes

NAME OF CONTRACTOR

Smart

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



8TH ST. S.W.

N.

TREMONT
AVE.
S.W.

M.H.

SIGNED

John E. Shover
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6/19/39

REMARKS:

Replaced old lateral - root trouble -

2/13

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

No. 4038

MASSILLON, OHIO, 5/18 19

RECEIVED OF

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.