

11
26

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº. 4039

DATE INSPECTED 5/26/39

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. STADIUM-5 SIPPON PARK.

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

259' 8" d

WAS LATERAL AT CURB?

Yes

WAS ATTACHED TO MAIN


Yes

NAME OF CONTRACTOR

T. Palone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

S. SIPPON PARK,



O.M.H.

SIGNED

John E. Brown
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

5/26/39

REMARKS:

OK
G.C.W.

NOT TO BE ANSWERED BY INSPECTOR
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
N^o 4039
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5-25 19
RECEIVED OF J. Lauterbach FEE OF \$

FOR WHICH PERMISSION IS GRANTED Board of Education

TO TAP Sanitary SEWER ON THE West side of

OF New Stanton AVE., TYPE OF STREET St.

THE PREMISES BEING LOT No. South Sippo Park House No. Stadium

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Tray Palmer

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.