

11
21

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4040


DATE INSPECTED 5/25/39 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 60

HOUSE NO. STADIUM, S. SIPPON PARK, DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 60 ~ 8"

SIZE OF PIPE USED 6" WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR Tony Palone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED John E. Shiner FILED AT ENGINEER'S OFFICE 5/26/39
INSPECTOR FOR CITY

REMARKS:

OK
G.C.W.

NOT TO BE ANSWERED BY INSPECTOR
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO 4040

PERMIT TO TAP SEWER

DATE RECEIVED 5-25 19
MASSILLON, OHIO

RECEIVED OF

G. Hutzsch

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Board of Education

TO TAP

Sanitary

SEWER. ON THE

West side of

OF

New Stadium South Side Park

TYPE OF STREET

St.

THE PREMISES BEING LOT No.

Stadium

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Tony Polone

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.