

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4054

DATE INSPECTED 8/11/39

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

186

HOUSE NO. 217

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

186 - 8'd

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

Yes

WAS ATTACHED TO MAIN


Yes

NAME OF CONTRACTOR

Tony Palone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

NORTH, AVE. N.E.



186'

0 MH

SIGNED

John E. Egan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

8/14/39

REMARKS:

PUT IN Y. AT 50' AT BACK SIDE OF WALK.

86-0-522
86A-800
Red gear

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4054
PERMIT TO TAP SEWER

MASSILLON, OHIO, 1919
RECEIVED OF W. B. Palmer FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED W. B. Palmer

TO TAP San SEWER ON THE East

OF North E AVE., TYPE OF STREET Chapel
ST.,

THE PREMISES BEING LOT No. 86 HOUSE No. 217

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR W. B. Palmer

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.