

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

N^o. 4071

AND SIGNED WHEN RETURNED

~~No Record~~

DATE INSPECTED 11/10/39

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

127

6" 6" d

11/51

HOUSE NO. 519

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

57'

SIZE OF PIPE USED 4" UP


WAS LATERAL AT CURB? N^o

NAME OF CONTRACTOR

Geo. Easley

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED:



4th ST. S.E.

0.2 127'

6" 6" d at M^o
57'

SIGNED

John Easley
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

11/10/39

REMARKS:

01
61
1

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4071
PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/7

RECEIVED OF

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

Wages 7/1/40 8.00
B. O. Galindo