

✓
10
4

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

№ 4072

DATE INSPECTED 11/15/39

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM** _____

HOUSE NO. 528

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH** _____

SIZE OF PIPE USED 6"


110' - 7'd

WAS LATERAL AT CURB? Yes

NAME OF CONTRACTOR Smart

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED John E. Hinner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

11/15/39

REMARKS: Wye pole still sticking up when lateral was uncovered measurements ok

10
4

NOT TO BE ANSWERED BY INSPECTOR
NO. 4072

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

DATE OF PERMIT 11/14 19
MASSILLON, OHIO.
RECEIVED OF John W. Hoffman FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED John W. Hoffman
TO TAP Sanitary SEWER, ON THE East
OF 26th St. S.E. AVE., TYPE OF STREET dirt
THE PREMISES BEING LOT No. 6916 HOUSE No. 528

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. H. Amant

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.