

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4076

3/9

DATE INSPECTED 11/29/39

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 131

HOUSE NO. 928


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 131 — 5' 6" d

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Geo Earley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
ROOSEVELT AVE. NE.



OK
G.C.W.

SIGNED John Chamer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

11/29

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4076
PERMIT TO TAP SEWER

MASSILLON, OHIO, 11-29 19

RECEIVED OF

Bryon Burd

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

Geo. Early

TO TAP

Sanitary

SEWER, ON THE

East

OF

Pennett St

AVE.,
ST.,

TYPE OF STREET

Dist

THE PREMISES BEING LOT No.

7031

HOUSE No.

928

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Geo. Early

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.