

1/5

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

Nº 4083

DATE INSPECTED 12/14/39

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

75'

HOUSE NO. 510

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

75'

5' d

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? Yes


NAME OF CONTRACTOR

Geo Earley

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

LINCOLN WAY. E.



SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

RELAI D LINE FROM CURB TO WALK 12'

OK  
GCW

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE.

NO. 4083

# PERMIT TO TAP SEWER

1:00 o'clock

DATE OF PERMIT

MASSILLON, OHIO.

12/14

15

RECEIVED OF

*Her Early*

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

*Thos. Botton*

TO TAP

*Sanitary*

SEWER, ON THE

*North*

OF

*Lincoln Way E.*

AVE.,  
ST.,

TYPE OF STREET

*road*

THE PREMISES BEING LOT No.

*155*

House No.

*510*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

*Her Early*

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.