FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 4088 AND SIGNED WHEN RETURNED DATE INSPECTED 2/17/40 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM House No. 12 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT SIZE OF PIPE USED CURB LINE AND DEPTH WAS LATERAL AT CURB? NO NAME OF CONTRACTOR I COMM WAS ATTACHED TO MAIN ME SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED LAKE AVE NW SIGNED REMARKS: TAPED TO MAIN.

$N_{\rm c}^{ m o}$ of public service $N_{\rm c}^{ m o}$ of 4088

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Name of Contractor TENEY POLENE BY DOC

Note. This permit covers work outside of building only. Any work inside to of building is subject to Massillon Board of Health Regulations.