

9
26

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4090

DATE INSPECTED 2/29/40

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

215'

HOUSE NO. 1724

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

215' 6" d

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? Yes


NAME OF CONTRACTOR

Smart

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

TREMONT AVE W.



N
26

SIGNED

John Thomas
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

O.M.H.

2/29/40

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4090
PERMIT TO TAP SEWER

DATE OF PERMIT 4/26/19

MASSILLON, OHIO,

19

RECEIVED OF

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET

St.,

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.