

10
/ 10

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4091

DATE INSPECTED 3/9/40

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. R. 31 FEDERAL AVE.

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR Geo. Carley.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

MARKET ALLEY, N.W.

SIGNED John E. Hume

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

3/11/40

OK
GC

REMARKS:

TAPED IN M. H. RAN TO EAST. SIDE. OF BUILDING
1' AWAY.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4091
PERMIT TO TAP SEWER

MASSILLON, OHIO,

March 9 19

RECEIVED OF

J. Early

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

For

TO TAP

San

SEWER, ON THE

North

OF

Market Hall Alley

AVE., TYPE OF STREET

drift

THE PREMISES BEING LOT No.

100

HOUSE No.

R 31 Federal

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Early

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.