

10
8

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o. 4113

DATE INSPECTED 5/11/40

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 23

HOUSE No. 345 VIRGINIA AVE S.E.

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 23 - 6'6"

SIZE OF PIPE USED 6" UP


WAS LATERAL AT CURB? Yes

NAME OF CONTRACTOR Geo. Earley

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

WILSON AVE. S.E.



SIGNED John Elmer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

5/13/40

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
N^o 4113 PERMIT TO TAP SEWER

DATE ISSUED 5/10 1919
MASSILLON, OHIO,

RECEIVED OF Ralph Feather FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Ralph Feather

TO TAP Sanitary SEWER, ON THE South

OF Wilsons Ave. S.E. AVE., TYPE OF STREET dirt
ST.,

THE PREMISES BEING LOT No. 6953 House No. 345 Virginia

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Her. Farley

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.

*8/15/40 - \$8.00
New account*