

~~MAILED~~

2/3

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4127

DATE INSPECTED 6/13/40

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

130

HOUSE NO. _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

130

SIZE OF PIPE USED 4"


WAS LATERAL AT CURB? _____

NAME OF CONTRACTOR

Geo Earley

WAS ATTACHED TO MAIN _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

John E. Brown

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6/13/40

REMARKS:

RELAY LATERAL FROM MAIN TO WALK

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO. 4127

PERMIT TO TAP SEWER

MASSILLON, OHIO,

6-12

19

RECEIVED OF

Peoples Bldg. & Loan

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Delbert Earley

TO TAP

Sanitary

SEWER ON THE

East

OF

2nd ST N.E

AVE.,
ST.,

TYPE OF STREET

Gravel

THE PREMISES BEING LOT No.

659

HOUSE No.

318

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Del Earley

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

*Installed gas
Relaying lateral.*