

8

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 4129

DATE INSPECTED

6/18/40

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

7'

HOUSE NO.

2512

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

7' 9' 6" d.

WAS LATERAL AT CURB?

Yes

NAME OF CONTRACTOR


Smart

WAS ATTACHED TO MAIN

Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

LINCOLN WAY, N.W.



SIGNED

John P. [Signature]
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6/18/40

REMARKS:

9/8
\$1000
10/1/40
New account

NOTED BY INSPECTOR
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
N^o 4129
PERMIT TO TAP SEWER

MASSILLON, OHIO, 6-17 1940

RECEIVED OF John Wetzel FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED L. Smart

TO TAP Sanitary SEWER ON THE North

OF Lincoln Way N.W. AVE., TYPE OF STREET Brick
ST.,

THE PREMISES BEING LOT No. 7063 House No. 7751

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. Smart

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.