

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4131

DATE INSPECTED 6/21/40

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

70

HOUSE NO. 905

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

70 - 8'6" d.

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

Yes

NAME OF CONTRACTOR


Tony Palone

WAS ATTACHED TO MAIN

Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

7TH ST. S.W.



OVERLOOK AVE.

① M.H.

SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6/24/40

REMARKS:

Tony had to tear up line & relay same, was laid at first w
out inspection

Relaying sewer lateral

2/15

Relaying Sewer Lateral

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4131
PERMIT TO TAP SEWER

DATE ISSUED 6/20 1920
MASSILLON, OHIO.
RECEIVED OF Bob H. H. H. FEE OF \$ 7.25
FOR WHICH PERMISSION IS GRANTED Plaza Building
TO TAP Plaza Building SEWER, ON THE Street
OF 7th St. N.E. AVE., TYPE OF STREET St.
THE PREMISES BEING LOT No. 2321 House No. 905

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Long P. Co.

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.