FOLLOWING DATA TO BE ANSWERED BY INSPECTOR N^o_{\cdot} AND SIGNED WHEN RETURNED

DATE INSPECTED 7-31-40	- IF SO HOW AND LOCATION FROM 24° From MH. 50, 6° Deap at Property Manhole Down Stream 24° From MH. 50, 6° Deap at Property
House No. 319 Size of PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	NAME OF CONTRACTOR 1011 Palone
Was attached to main VES Show by diagram relation of La	TERAL TO WALL OF BUILDING SERVED.
Je Jute with Gall Tite	1.7'Below ->>
TOURS OF THE SECTION OF THE SECTION COURSES	
1- 26 E- 21	- 16 - 16 - 1
SIGNED SAELACO INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE 8/1/40
REMARKS: 1 of at. Prop. (11) e 1	Gi-solofsosideHouse a militalia

office of the director of public service \mathbb{N}^0 4144 PERMIT TO TAP SEWER

	, the second of	arāci (I
Flow line 1137 14 under floor 9.93	RECEIVED OF Jees of	18
1.44 1.44 Fall in 38°	FOR WHICH PERMISSION IS GRANTED	EXEC
X	TO TAP SEWER. ON THE	naVV
Rod 1.83	OF AVE., Type OF STREET ST.,	
Fleor 6.7 1Under 1.4	THE PREMISES BEING LOT NO. HOUSE NO. HOUSE NO. WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CIT	TY COUNCIL
9.9	RULES OF THE DEPARTMENT OF PUBLIC SERVICE. NAME OF CONTRACTOR	
	Note. This permit covers work outside of building only. Any wor	k inside
	of building is subject to Massillon Board of Health Regulations.	SWST-