

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4145

DATE INSPECTED 8-2-40

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

HOUSE NO. 607

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 4"

37° from M.H. on 6th. 6' Deep at

WAS LATERAL AT CURB?


NAME OF CONTRACTOR

Neale & Palone

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lat. at main connected with
EL. To stack. Found trouble
in 1st pipe back of EL. poor joint. Garage
cement in joint was pushed up in flow
line 2 1/2" inches. Retarding flow.



SIGNED

[Signature]

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

8/2/40

REMARKS:

Pipe replaced with cork-tite joints

MS 1017 SW

OK

See last page 800 is the morning
10-31
Replacing Sewer Line

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4145
PERMIT TO TAP SEWER

MASSILLON, OHIO, 8-1 1919
RECEIVED OF Tony Tulian FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Tony Palone
TO TAP Sanitary SEWER ON THE Alley South of Neal
OF Alley Ground AVE., TYPE OF STREET St.
THE PREMISES BEING LOT No. 5720 House No. 607
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Tony Palone

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.