

✓
4-1

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4146

DATE INSPECTED 8-9-40

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

222° From what 2nd ledge str.

HOUSE NO. 231

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

220° From rd at 2nd stat curb

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

50° Side
Walk

NAME OF CONTRACTOR


Smart

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lat. at walk is 1° West from I.P.
on west side of W. P.L.

There was a 2" x 6" wye pole at
end of lateral at edge of walk.
Asp. belts used for joints.
Plenty of fall.



SIGNED

Shortner

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

8/14/40

REMARKS:

1937
Ledger - 10-1-40 \$800
New account

Smart at first dug on inside of curb
and couldn't find lat. Harry Piper found it by
proding with small rod. then Smart followed line
and found wye pole on S. side of walk 12 West of N.E.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No 4146
PERMIT TO TAP SEWER

MASSILLON, OHIO, 8-8 1937
RECEIVED OF Joseph H. Cline FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Leo Smart
TO TAP Sanitary SEWER ON THE South
OF Norman Blvd. N.E. AVE., TYPE OF STREET Brick
ST.
THE PREMISES BEING LOT No. 7797 HOUSE No. 231
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR L. Smart

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.