

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4154

DATE INSPECTED 9/4/40

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

176

HOUSE NO. 2517

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

176 — 7'6" d


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Earley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-4-40

REMARKS:

OK CER

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4154

PERMIT TO TAP SEWER

MASSILLON, OHIO,

9-3

19

RECEIVED OF

W. J. Clements

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Geo. EARLY

TO TAP

San. Sewer

SEWER, ON THE

South

OF

Rhode Island

AVE., TYPE OF STREET

Gravel

THE PREMISES BEING LOT No.

4506 - 4507

House No.

2517

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Geo. EARLY

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

*Est. 10-18 \$200
Ledger 11/15/40
New account.*