Nº 4164

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

47

DATE INSPECTED 10/9/40	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. REAR 1612		
SIZE OF DIDE LICED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	E LOU MINICH SE PATERION IN DRAWFED	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	-
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.	
· WALNUT.	RR 5 5, 45 12 11	
3	#180 18 6" P.Pe	
UOD YTH BHT YO DEED Y DIO	8º Deep	
PAR O	060	
SIGNED John Ehm INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE 10/14/40	600
REMARKS: LATERAL STAL	RT. 25 BACK, OF, CURB.	

Nº 4164

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

DATE INSPECTO
MASSILLON, OHIO, 193
RECEIVED OF CONTRACT BANGE FEE OF \$ 200
FOR WHICH PERMISSION IS GRANTED
NAME OF CONTRACTOR
TO TAP SEWER. ON THE SIDE
OF AVE., TYPE OF STREET
THE PREMISES BEING LOT NO.
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR L.) Imant

Note. This permit covers work outside of building only. Any work inside walls

of building is subject to Massillon Board of Health Regulations.