

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4167

DATE INSPECTED 10/2/40

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

2'

HOUSE NO. 1118

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

2' 4' 6" d

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes


NAME OF CONTRACTOR

Earley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

1118 ST. N.E.

← N



M.H. 10

← 2' →

SIGNED

John E. Hurst
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10/3/40

REMARKS:

No. 4167

PERMIT TO TAP SEWER

New. acc. Rate \$800
Entered - Ledger Jan 1, 1941

DATE ISSUED 1/12/41
LOCATION FROM

MASSILLON, OHIO,

15

RECEIVED OF

B. Farley

FEE OF \$2

FOR WHICH PERMISSION IS GRANTED

Karl Seimetz

TO TAP

San

SEWER. ON THE

East

OF

1128 7th E.

AVE.,
ST.

TYPE OF STREET

Parcel

THE PREMISES BEING LOT No.

7473

House No.

1118

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

B. Farley

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.