## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 4170 AND SIGNED WHEN RETURNED DATE INSPECTED 10/7/ IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM House No .\_ DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 10 0343035 SIZE OF PIPE USED CURB LINE AND DEPTH ... DETHASE EL ROISI $oldsymbol{\mathcal{O}}$ SER NORW NAME OF CONTRACTOR \_\_ WAS ATTACHED TO MAIN. SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDI GAS. STATOTIL CABI SIGNED FILED AT ENGINEER'S OFFICE REMARKS: CONNIECTED TO REAR OF HOUSE TO CABINS IN REA

STONES GAS STAION.

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		мона коптоол о			10/0/g =	TACE
1 1	Received of	ALANASIA	MA	SSILLON, OHIO,	pee of	1\$ \$
	FOR WHICH PERMISS	SION IS GRANTED	edago des la La AAA São avidi	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ores by 4 50 <del>Comportus (</del>	
	TO TAP_	2.19/21		., Type of Street	or oreogra- - The	
1. 1 <sub>1</sub>	THE PREMISES BEING		) //// \	House No.	2/2	4
	WORK TO BE DONE RULES OF THE DEP	ARTMENT OF PUBLI		o. 2323, duly pas	SED BY THE CIT	Y COUNCIL
	in in the second se	is permit covers	s work outside	of building onl	y. Any wor	k inside

of building is subject to Massillon Board of Health Regulations.