

2
39

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 4171

DATE INSPECTED 10-11-40

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

234

HOUSE No. 423

DISTANCE FROM FIRST MANHOLE

SIZE OF PIPE USED 6"

DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

234

11' d

WAS LATERAL AT CURB? NO.



NAME OF CONTRACTOR

TONY POLONE
Back St. Bldg

WAS ATTACHED TO MAIN YES

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SOUTH AVE. SE. CONVENT



SIGNED. Shertzer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

11-5-40

REMARKS:

NOT TO BE ANSWERED BY INSPECTOR
NO. 4171

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

No Change in Rate.

DATE 10/7

MASSILLON, OHIO.

19

RECEIVED OF

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
St.

THE PREMISES BEING LOT No.

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.