

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4183

DATE INSPECTED 12-23-40

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

75' North of M.H.

HOUSE NO. 908

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

59' North of curb

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? No


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Delbert Earley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral is 7.5' ^{Deep} at Building
4' of pipe was connected to existing lateral



Bennington Ave. N.E.

SIGNED

J. L. ...
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

11/4/41

REMARKS:

G.C.U.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4183

PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/23 1923

RECEIVED OF Delbert Early

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED On Rockingham

TO TAP Sanitary

SEWER. ON THE North

OF Bennington Ave NE

AVE.
ST.

TYPE OF STREET deint

THE PREMISES BEING LOT No. 8520

HOUSE No. 908

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Delbert Early

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

*New account
Entered in ledger 7/1/41
Joo*