

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
Nº 4191 AND SIGNED WHEN RETURNED**

DATE INSPECTED 2-26-41

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

382' East

HOUSE NO. New House

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

382'

SIZE OF PIPE USED 4"


WAS LATERAL AT CURB? yes.

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Delbert Early

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Julius Mohan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: No Basement under this house. Plumbing in Sewer has met existing soil pipe set by plumber

TO BE ANSWERED BY INSPECTOR
NO. 4191

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 2/26 1929

RECEIVED OF Henry Parby

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Marvin Tamm

TO TAP Sanitary

SEWER. ON THE South

OF Yale Ave. N.E.

AVE., TYPE OF STREET dirt
ST.,

THE PREMISES BEING LOT NO. ~~7096~~ 7396

HOUSE NO. 1029

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Delbert Parby

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.

New account \$900

102
Ledger May 15, 1929