## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 4195 AND SIGNED WHEN RETURNED

	5-1
<u></u>	orb'/i
36	≥nt
	N —/
	Ġ

DATE INSPECTED IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 305 House No.\_ DOWN STREAM TO DITCH AT SIZE OF PIPE USED CURB LINE AND DEPTH WAS LATERAL AT CURB? NAME OF CONTRACTOR WAS ATTACHED TO MAIN SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. Lateral 45 Deepardurbline Lateral 6 Deep at house Lateral 51' Long SIGNED FILED AT ENGINEER'S OFFICE REMARKS

## PERMIT TO TAP SEWER

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC-SERVICE. NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.