

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 4197

DATE INSPECTED 3-15-41

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 87.5' As Shown below

HOUSE No. 1058

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 4"


WAS LATERAL AT CURB?

NAME OF CONTRACTOR

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 5.5' Deep at main line
Lateral 5' Deep at curb line
8' of lateral Relaid



sewer → ROSLYN AVE. N.E.

SIGNED Julius Anderson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 3/22/41

REMARKS: Existing lateral Repaired From main line to curb

OK

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4197

PERMIT TO TAP SEWER

MASSILLON, OHIO,

3-15

RECEIVED OF

Mrs. C. E. Brown

FEE OF \$

2.1

FOR WHICH PERMISSION IS GRANTED

D. Earley

TO TAP

Sanitary

SEWER, ON THE

North

OF

Rocky Lane NE

AVE., TYPE OF STREET

Gravel

THE PREMISES BEING LOT No.

1221

HOUSE No.

1058

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE

NAME OF CONTRACTOR

D. Earley

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

*Repairing lateral from curb,
No Change in Path.*