

9/27

DIRECTOR OF PUBLIC SERVICE

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 4200

DATE INSPECTED 4-1-41

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

House No. 2059

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

20° West from 17H: 7° Deep edge of

WAS LATERAL AT CURB? YES.

NAME OF CONTRACTOR

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.


L.A. SMO

KAKTITE JOINTS WITH JUTE USED

Plenty of fall. Ran sewer cable thru. and
found line clear.

TREMONT AVE.

SW



SIGNED

Shorthouse

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

4/4/41

REMARKS:

LATERAL IS USED Lot at so. Edge Paving is on line with E side of Ho

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4200

PERMIT TO TAP SEWER

Owner R. A. Cassler

MASSILLON, OHIO, Mar 24 1911

RECEIVED OF L. Smart

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED L. H. Smart

TO TAP San SEWER ON THE South

OF Tremont Ave SW AVE., TYPE OF STREET Asp. on Brick
ST.,

THE PREMISES BEING LOT No. 10335 HOUSE No. 2049

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. H. Smart

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

1 inch 8.00
4-1-4 Date

New account.

Entered - Ledger 4/1/41