

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4201

6
46

DATE INSPECTED 4-1-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

46' center of Street

HOUSE NO. 1312

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

yes.

WAS ATTACHED TO MAIN


No.

NAME OF CONTRACTOR

Tony Palome

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 8' Deep at curb
Lateral 6'5" Deep at house
Lateral 69' Long house to curb



SIGNED

Julius Holman
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OK

REMARKS

cellar dug. No house on lot. X Marked on top of curb
Note tie in. MH. to Lateral at house

New record
Entered in ledger 7/1/41
Rate 8.00

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4201
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3-26 1941
RECEIVED OF O. J. McNamee FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Tony Palone
TO TAP Sanitary SEWER, ON THE North
OF Lincoln Ave NE AVE., TYPE OF STREET Brick
ST.,
THE PREMISES BEING LOT No. 8781 HOUSE No. 1312
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Tony Palone

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.