

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

N^o. 4214

AND SIGNED WHEN RETURNED

DATE INSPECTED 4-25-41

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. No house on lot

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? yes

NAME OF CONTRACTOR T. Palone

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. S.

Lateral 7' Deep at curb line N. →
Lateral 6' Deep at house
Lateral 45' Long. House to curb line
ditch line



22nd St S.W.

SIGNED Julius Swenson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 4-26-41

REMARKS: Note tie in first house north #329 corner. to lateral

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4214
PERMIT TO TAP SEWER

DATE WHEN FIRST MAJOR WORK BEGAN

MASSILLON, OHIO, 1/24

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE.,
ST.,

TYPE OF STREET

THE PREMISES BEING LOT No.

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.