

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

787
745
42

Nº 4239

DATE INSPECTED 6-10-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

40' out in street

HOUSE NO. 827

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? yes, 4' from curb under walk

NAME OF CONTRACTOR

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 8' Deep at sidewalk.
Lateral 8' Deep at house
Lateral 48' Long house to sidewalk.



SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Combination curb and walk + mark on sidewalk
Note: Tied in from next house west, #825 cellar was not dug

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

NO. 4239

DATE ISSUED 4/10
 MASSILLON, OHIO, 11

RECEIVED OF D. E. Ensey FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Robert Babcock

TO TAP San SEWER ON THE St.

OF Lab. St. AVE., TYPE OF STREET St.

THE PREMISES BEING LOT NO. H. 118 HOUSE NO. 127

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR D. E. Ensey

Note. This permit covers work outside of building only. Any work inside
 of building is subject to Massillon Board of Health Regulations.

*New account.
 ledger 10/1/14
 Rate 8.20*