

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4250

DATE INSPECTED 7-18-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

HOUSE NO. 758

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? No

WAS ATTACHED TO MT. Yes

NAME OF CONTRACTOR Tony Polone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 7' Deep at Mt.
Lateral 6.5' Deep at curb.
5.5' Deep Mt. in yard
50' Long Mt. in yard to Mt. in street
41' Long Mt. in yard to curb.



SIGNED Julius Carlson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE July 21 1941

REMARKS: was attached to Mt. in State Ave N.E.

NOT TO BE SIGNED BY INSPECTOR

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 4250

PERMIT TO TAP SEWER

DATE WHEN AND LOCATION FROM
FIRST PARAPHRASE DOWNS STREET

MASSILLON, OHIO.

7/12

RECEIVED OF

C. E. Rice

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

C. E. Rice

TO TAP

storm

SEWER, ON THE

South

OF

State Ave N.E

AVE., TYPE OF STREET

park

THE PREMISES BEING LOT No.

866

HOUSE No.

758 Arbor

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Long Palmer

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

No change in Rate.
Sewer in yard to storm
sewer.