

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

Nº 4253

AND SIGNED WHEN RETURNED

No Inspector on this job

Measurements taken 8-19-41

DATE INSPECTED

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

69.5' center of side walk

HOUSE NO.

DISTANCE FROM FIRST MANHOLE

SIZE OF PIPE USED

6"

DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

RECEIVED OF

WAS LATERAL AT CURB?

under

NAME OF CONTRACTOR

Smart

WAS ATTACHED TO MAIN


side walk

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 8' Deep at side walk.

Lateral 7' Deep at house

Lateral 97.5' Long house to side walk



Side walk sewer

69.5'

18"

← sewer

Grass space

Lincoln way W.

SIGNED

Julius Tolson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

AKGOW 8-20-41

REMARKS:

Main sewer under side walk

LOVE

Contractor did not notify the city for an inspector and line was laid without inspection. Measurements taken on top of ground.

R. F. Snyder

New account, Rate 800
x ledger Jan 1942

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4253
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/17 1942

RECEIVED OF J. J. Snyder FEE OF \$ 2.50

FOR WHICH PERMISSION IS GRANTED

TO TAP San SEWER, ON THE

OF Lincoln Ave. AVE., TYPE OF STREET Parade
ST.

THE PREMISES BEING LOT No. 10200 House No. 7964

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. J. Snyder

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.