FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-18-41	SO HOW AND LOCATION FROM 66' OUT IN STREET "UP STE
House No. 1872	
DO DO	STANCE FROM FIRST MANHOLE WN STREAM TO DITCH AT RB LINE AND DEPTH
Was Lateral at curb? Ves.	
NA WAS ATTACHED TO MAIN	ME OF CONTRACTOR $EaFleY$, A
SHOW BY DIAGRAM RELATION OF LATERA	L to wall of building served. PeS . E
Lateral 7'Deep atou	tbline
Lateral, 6's Deep at he	005e
Loterolso' Long house	e tocorbline / NPorch S
MODELLE CONTRACTOR OF THE SECOND TO SECOND THE SECOND TO SECOND THE SECOND TH	amono my by hine in and 16 sil
10000	16-24 CCE
Tremont	-AVE.3E
SIGNED Julius molson	FILED AT ENGINEER'S OFFICE July 21 1941
INSPECTOR FOR CITY	
REMARKS	ricangerilistica di insvilio di toli interiore

Nº 4255

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Meny northoes esta Work of the Line 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	MASSILLON, OHIO,
	A E L L L L L L L L L L L L L L L L L L
	RECEIVED OF FEE OF 5
	FOR WHICH PERMISSION IS GRANTED
	ho and $ ho$ compared to be defined to the second section of $ ho$ and $ ho$
	TO TAP
	OF AVE., TYPE OF STREET
1.16	THE PREMISES BEING LOT No.
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC
. j.	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
	Name of Contractor
	NAME OF CONTRACTOR
	Note. This permit covers work outside of building only. Any work inside
- f	of building is subject to Massillon Board of Health Regulations.