	FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
	N_{\cdot}^{0} 4256 AND SIGNED WHEN RETURNED
elleor *	DATE INSPECTED 4-2-4/ IF SO HOW AND LOCATION FROM Connected to Stubin M. Dead E
	House No. 27/6 Distance from first manhole Down stream to ditch at Cure line and depth
V	Vas Lateral at curb? No Name of Contractor F.J. Lamonica Ves. Name of Contractor F.J. Lamonica Vas attached to Main to Stubin MH.
	Show by diagram relation of lateral to wall of building served. ET Res. w. Lateral 12' Deep at stub in Mt.
	Lateral 7'Deepathouse to M.
A. nosac	Clean & Ling clean out
	LSERVEY DeadEnd.
Idava dažajo	FILED AT ENGINEER'S OFFICE AUGUSTON OK G
F	remarks. Both clean nute are 4' off dotted line one west ane Ea This sketch is from Rear of Building

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, THE PREMISES BEING LOT No. 15 4 5 1 WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

NAME OF CONTRACTOR