

1
2
L

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4259

DATE INSPECTED 8-9-41

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM connected straight to MH.

HOUSE NO. 26

DISTANCE FROM FIRST MANHOLE

SIZE OF PIPE USED 6"

DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH

WAS LATERAL AT CURB? connected

NAME OF CONTRACTOR Lamonia

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 10.5' Deep at MH. connection

Lateral 6.5' Deep at corner of house

Lateral 50' Long corner house to MH.

no curb curb line

27th St NE

Mt. 1/8 Bend
Dead End MH.

SIGNED

Julius Holson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OKGCW - Aug 13 19

REMARKS:

connected to invert in Mt.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4259

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/31

RECEIVED OF

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

New
Hedges 11/15/41
Pat 800