

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4266

7
31
✓

DATE INSPECTED 8-22-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

39' out in street

HOUSE NO. 363

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? Y=3.


NAME OF CONTRACTOR Palone

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 7' Deep at curb line
Lateral 7' Deep at house
Lateral 39' Long house to curb line

N. →



no curb

Schule Ave. NW.

Schule Ave. NW.

SIGNED Julius Holson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE OK GCW Aug 22 1941

REMARKS: Nature of soil "Red clay Hard pan"

7/31

NOT TO BE ANSWERED BY INSPECTOR

NO. 4266

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

DATE INSPECTED
FIRST RABBIT DOWN STREAM

MASSILLON, OHIO.

7/19

19

RECEIVED OF

Paul R. R. R.

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

Tony Paloma

TO TAP

26" dia. V.A.

SEWER ON THE

26" dia. V.A.

OF

26" dia. V.A.

AVE.,
ST.,

TYPE OF STREET

26" dia. V.A.

THE PREMISES BEING LOT NO.

7707

HOUSE NO.

315

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Tony Paloma

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.