

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4271

DATE INSPECTED 9-3-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

262' out in Street.

HOUSE NO. 130

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN yes "Hub Saddle"

NAME OF CONTRACTOR Palone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral / 9' Deep at main line
Lateral / 8' Deep at curb
Lateral / 24' Long house to curb
Lateral / 41' Long house to main



SIGNED Julius Malcom
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE OK GCW - Sept 8

REMARKS: Soil Mixed Sand gravel & clay This line was put in to get ce drainage, another line is connected to the bath, still in operation.

*No Change in Rate.
2/34
Sewer Drains.*

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4271
PERMIT TO TAP SEWER

MASSILLON, OHIO, 729 1924
RECEIVED OF Tommy Malone FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Plas B. Lenniger
TO TAP Sanitary SEWER ON THE North
OF Thorne Ave. N.E. AVE., TYPE OF STREET dist
ST.,
THE PREMISES BEING LOT No. 636 HOUSE No. 130
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Tommy Malone

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.