FOLLOWING DATA TO BE ANSWERED BY INSPECTOR N_{\star}^{o} 42.72 AND SIGNED WHEN RETURNED

	살림 어느는 얼마는 말로 하는 말로 가는 그를 모르는 것 같다.
DATE INSPECTED 7-8-41	FIRST MANHOLE DOWN STREAM 39' OUT IN STreet
since and a second second	FIRST MANHOLE DOWN STREAM
House No. 1/67	[전략: [4] 말리 보고 등록 등로 보고 보고 있는 말리는 그는 그리고 보고 있다.
William to the second of the s	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 38 CRYBBB
SIZE OF PIPE USED	CURB LINE AND DEPTH
Was Lateral at Curby Yes.	— and fair and correspond to the second state from the second second second second second second second second
	NAME OF CONTRACTOR POTONE
Was attached to main	and the second of the second o
SHOW BY DIAGRAM RELATION OF L	ATERAL TO WALL OF BUILDING SERVED.
Lateral 8.5" Deep at	Curb
Lateral 8' Deep at	
ricial necbal	10050
Laleral 72' Longhou	10-7-0-1-2
is in the Carlo are the Carlo Carlo Carlo and a carlo Carlo and a carlo carlo and a carlo carlo carlo carlo car	sis moderated territoria and analysis and forest on the second seconds.
	-4464-5
	Lennox AVEN.E.
SIGNED (Julius molson	TFILED AT ENGINEER'S OFFICE DK GCW Sept 11
INSPECTOR FOR CITY	The A Lighter Office 305
REMARKS + MOFK ON TOD	ofouth Soil hard clay"

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

india di Amerika di Albanda di Amerika di Am Amerika di Amerika di	IE RWOG GLOBHAU 1	MASSILLON	і, Оніо,	/ 7
Tools	AREAT AND TO AREAD IN	1		india saudy
RECEIVED OF	A Commence of the Commence of	<u> </u>	e de la companya della companya della companya de la companya della companya dell	FEE OF \$
		and I want	PD	
OR WHICH PERMISSION IS (GRANTED.	1.1.		
			Linan S	geor al a ave
O TAP	S Ash	EWER. ON THE		
77,	1 1/10 2	~		
FLEMME	Y // Chell	SAVE., TYPE	OF STREET	- A-land W
HE PREMISES BEING LOT NO	o. 88119		House No	1167

NAME OF CONTRACTOR JAMA Calana

Note. This permit/covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.