

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4273

DATE INSPECTED 9-12-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

156' out in Street

HOUSE NO.

444

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

yes.


NAME OF CONTRACTOR

Earley

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. N

Lateral 7' deep at connection
Lateral 6' Deep at curb
Lateral 48' Long house to curb.
60' laid house to connection



SEWER →

18th N.W.

SIGNED

Julius Tolson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OK GCW. Sept 16

REMARKS.

+ mark on top of curb. Soil clay to Rock

Had 10 of lateral in place when I found it. Took levels and found that soil pipe would just go under 10th block. Told Carpenter Contr. and he said O.K. - give it all the fall possible. Dug out in street but did not take out last pipe which would have given 18" more depth. Said it was in solid rock.

D. Earley - J. Nelson, D. Shertzer & Sewer ditch Contr.
 9/12/41 P.M. H. Earley
 Witnesses

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
 No. 4273
PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/9 1941
 RECEIVED OF H. Earley FEE OF \$ 2.00
 FOR WHICH PERMISSION IS GRANTED H. Earley
 TO TAP 18th M.W. SEWER. ON THE 18th
 OF 18th M.W. AVE., TYPE OF STREET St.
 THE PREMISES BEING LOT No. 5052-53 House No. 444
 WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
 NAME OF CONTRACTOR H. Earley

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.