FOLLOWING DATA TO BE ANSWERED BY INSPECTOR -4289AND SIGNED WHEN RETURNED DATE INSPECTED 10-17-41 FIRST MANHOLE DOWN STREAM 173 OUT IN STEET House No.\_ DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT SIZE OF PIPE USED CURB LINE AND DEPTH WAS LATERAL AT CURB? YES NAME OF CONTRACTOR MO SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED Lateral 6 Deepat curbline Lateral 5'Deepathouse Lateral Hihouse To Eurbline hon Lateral 40 house to curbline 2nd Connection Warwick STN.W. FILED AT ENGINEER'S OFFICE DIC GCW Cor 21 4 REMARKS: Note Two(2) Connections going into house Soil mixed dir

	OFFICE OF THE DIRECTOR OF PUBLIC S  PERMIT TO TAP SEWE	78308 S
Gg.	MOSS MOTTAGE CHA VION OR THE MASSILLON, OHIO,	
	RECEIVED OF COLLAND Brown FEE C	or <b>\$</b> 2
	FOR WHICH PERMISSION IS GRANTED TO TO A STATE OF THE PROPERTY	
	TO TAP SEWER, ON THE	a eav
g g	OF Wasanch W Ave., Type of Street.	1
3 1	THE PREMISES BEING LOT No. 355	
303	Work to be done in accordance with Ordinance No. 2323, duly passed by the C Rules of the Department of Public Service.	ITY COUN
1/2	Name of Contractor Manager Manager	
	Note. This permit covers work outside of building only. Any wo of building is subject to Massillon Board of Health Regulations.	rk insid