

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 4291

DATE INSPECTED 10-8-41

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 19.5" out in street

HOUSE No. 323

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN yes. with wye

NAME OF CONTRACTOR Eatley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 6.5' Deep at main line
Lateral 6' Deep at curb
Lateral 6' Deep at house
Lateral 24' Long house to main line
Lateral 12' Long house to curb



SIGNED Julius Holson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE OK GCW **OCT 21**

REMARKS: + mark on top of curb Soil Gravel.

11/12

NOTED BY INSPECTION
TO BE ANSWERED BY INSPECTION
AND SIGNED
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4291
PERMIT TO TAP SEWER

Relay

by

DATE WHEN PERMIT WAS ISSUED 10/7 1915
MASSILLON, OHIO.
RECEIVED OF G. E. Earls FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Relay
TO TAP San SEWER ON THE 1016
OF 1016 AVE., TYPE OF STREET Dist
ST.,
THE PREMISES BEING LOT No. 1016 HOUSE No. 323

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Earls

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.