

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4293

DATE INSPECTED 10-10-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

3' out in street

HOUSE NO. _____

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes.



NAME OF CONTRACTOR

Palone

WAS ATTACHED TO MAIN _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 7.5' Deep at curb.
Lateral 7' Deep at house
Lateral 69' Long house to curb



Lennox Ave N.E.

SIGNED

Julius Holson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE OK GCU Oct 21

REMARKS.

Tied in from next house East. "foundation not up" "cellar d.
+ mark on top of curb soil. hard clay

6/16

NOT TO BE ANSWERED BY INSPECTOR

NO 4293

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

DATE WHEN PERMIT WAS ISSUED

MASSILLON, OHIO,

10/10

19

RECEIVED OF

T. J. Palmer

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

L. R. Barker

TO TAP

Same

SEWER, ON THE

77

OF

Franklin St.

AVE.,
ST.,

TYPE OF STREET

Public

THE PREMISES BEING LOT No.

5780

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

T. J. Palmer

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.