

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4296

DATE INSPECTED 11-10-41

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

114' out in street

HOUSE NO. 508

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes.

NAME OF CONTRACTOR

Smart


WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 7.5' Deep at curb

Lateral 8' Deep at house

Lateral 43' Long house to curb.



SIGNED

Julius Nelson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

11-17-41

OK GC

REMARKS:

+ mark on top of curb

Soil. clay.

11/18

NOT TO BE ANSWERED BY INSPECTOR

NO. 4296

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/18

RECEIVED OF L. H. Smart

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED C. B. Schuch

TO TAP San.

SEWER, ON THE E

OF 1916 N.Y.

AVE., TYPE OF STREET dist
ST.,

THE PREMISES BEING LOT No. 5092-91

HOUSE No. 508

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. H. Smart

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.