

Nº 4301

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

7  
30

DATE INSPECTED 12/2/41

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

70' To M.H. down N. str

HOUSE NO. 1741

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

70' 6' deep


WAS LATERAL AT CURB? Yes.

NAME OF CONTRACTOR

L. SMART.

WAS ATTACHED TO MAIN Yes.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

John E. Hurmer  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12-3-41- OK GCW

REMARKS:

Soil: Clay

# OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO. 4301

## PERMIT TO TAP SEWER

1/35

MASSILLON, OHIO, 11/28 19

RECEIVED OF Russell Baer FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Russell Baer

TO TAP Sanitary SEWER ON THE South

OF Main Ave. N. AVE., TYPE OF STREET dent  
ST.,

THE PREMISES BEING LOT No. 2831 HOUSE No. 1741

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. W. Amant

Note. This permit covers work outside of building only. Any work inside  
of building is subject to Massillon Board of Health Regulations.