

NO. 4304

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

10
21

DATE INSPECTED 12-31-41

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM Could not locate Mt. Sec Rel

HOUSE NO. 166

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH

WAS LATERAL AT CURB? Relaid Job

NAME OF CONTRACTOR Earley E.

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. N. Res. S.



SIGNED Julius Holson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE OK-GCW Jan 21

REMARKS: This lateral was relaid. Due to roots in every joint caused sewer stoppage
Soil clay

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO. 4304

PERMIT TO TAP SEWER

DATE 12/29 19
MASSILLON, OHIO,

RECEIVED OF Clinton Holmes FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED H. Farley

TO TAP Same SEWER, ON THE E.

OF 23rd St. E. AVE., TYPE OF STREET Dist.
ST.,

THE PREMISES BEING LOT No. 4368 HOUSE No. 166

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. Farley

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.

820

Relaying Old Line
No Change in Rate